



C of C  
SK

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of: )  
HIROSHI FUSE ) Examiner: Shik L.P. Ip  
Appl. No.: 10/767,721 ) Group Art Unit: 2837  
Filed: January 30, 2004 ) Confirmation No.: 6072  
For: DC MOTOR DRIVER )  
U.S. Patent No.: 6,922,029 B2 )  
Issued: July 26, 2005 ) October 3, 2005

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

**Certificate  
OCT 07 2005  
of Correction**

CERTIFICATE OF CORRECTION UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

10/04/2005 SSITHIB1 00000171 6922029

01 FC:1811

100.00 0P

OCT 11 2005

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



\_\_\_\_\_  
Lawrence A. Stahl  
Attorney for Patentee  
Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
Facsimile: (212) 218-2200

LAS:eyw

OCT 11 2005

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

Staple  
Here  
Only

PRINTER'S TRIM LINE

PATENT NO. : 6,922,029 B2

DATED : July 26, 2005

INVENTOR(S) : HIROSHI FUSE

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 8, "to" should read --for--.

Line 24, "signals" should read --signal--.

Line 52, "overloading," should read --overloaded,--.

COLUMN 2:

Line 11, "less" should read --is less--.

COLUMN 3:

Line 8, "become in" should be deleted.

Line 9, "coincidence" should read --coincide--.

COLUMN 4:

Line 65, "overloading," should read --overloaded,--.

COLUMN 5:

Line 55, "become at" should read --reach--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,922,029 B2

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)  
(Form#30)

Oct 11 2005

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,922,029 B2

DATED : July 26, 2005

INVENTOR(S) : HIROSHI FUSE

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6:

Line 41, "manner" should read --manner as--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,922,029 B2No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)  
(Form#30)

→ OCT 11 2005

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

Staple  
Here  
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,922,029 B2

DATED : July 26, 2005

INVENTOR(S) : HIROSHI FUSE

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 8, "to" should read --for--.

Line 24, "signals" should read --signal--.

Line 52, "overloading," should read --overloaded,--.

COLUMN 2:

Line 11, "less" should read --is less--.

COLUMN 3:

Line 8, "become in" should be deleted.

Line 9, "coincidence" should read --coincide--.

COLUMN 4:

Line 65, "overloading," should read --overloaded,--.

COLUMN 5:

Line 55, "become at" should read --reach--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,922,029 B2

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)  
(Form#30)

→ \_\_\_\_\_  
OCT 11 2005

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

Staple  
Here  
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,922,029 B2

DATED : July 26, 2005

INVENTOR(S) : HIROSHI FUSE

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

**COLUMN 6:**

Line 41, "manner" should read --manner as--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3801  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 6,922,029 B2

No. of add'l. copies  
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)  
(Form#30)

→ \_\_\_\_\_  
OCT 11 2005